

Joel Wichger's Response to Action Item #36

- a. All Rockwell-Collins GPS equipment outputs HIL or HPL, or an indication that RAIM is unavailable.
- b. As for FMS data, we encode NUCp as unknown.